

Work Order ID 112762

Thursday, February 06, 2014 12:41:34 PM

112762

Feb 24th

Page 1

Item ID: PB67-43001-225

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Bushing

Start Date: 2/6/2014 Start Qty: 72.00

72

Cust Item ID:

Required Date: 2/20/2014 Req'd Qty: 72.00

72

Customer:

Reference:

Approvals:

Process Plan: MFDate: 14-2-06

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
B67-43001	C

100

0.00

100

Hardinge

Hardinge CNC LATHE SMALL

Memo

0.00

Hardinge CNC Lathe Small

1-TURN AS PER FOLIO FA566 & DWG B67-43001

FOLIO REV: AADWG REV: C

2-DEBURR AS REQUIRED

(D40)
238 14-02-11
89
x72

110

0.00

110

QC

QC2- Inspect parts off machine FAI/FAIB

Memo

0.00

Quality Control

238 14-02-11
33

120

0.00

120

QC

QC8- Inspect parts - second check

Memo

0.00

Quality Control

72
FR 14/02/12

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data ☐									
Equip/Tooling ☐									
Operator ☐									
Material ☐									
Setup ☐									
Other ☐									
Process ☐									
Supplier ☐									
Training ☐									
Unapproved ☐									

FAULT CATEGORY

Landing Gear	General	Other
☐ Bending	☐ Bend	☐ Grain
☐ Centre Not Concentric to O/S	☐ BOM/Route	☐ Hardware
☐ Cracks	☐ Broken/Damaged	☐ Inspection Incomplete
☐ Crushed/Crimped.	☐ Burrs	☐ Instructions Incomplete/Unclear
☐ Cuffs	☐ Contamination	☐ Maintenance
☐ Heat Treat	☐ Countersink	☐ Mislabeled
☐ Inspection Strip in Tube	☐ Cut Too Short	☐ Misread
☐ Ripples in Bend	☐ Drill Holes	☐ Offset
☐ Torque Waves in Extrusion	☐ Drawing	☐ Out of Calibration
☐ Turning Sequence	☐ Finish	☐ Out of Sequence
☐ Wave/Twist in Tube	☐ Folio	☐ Outside Dimensions
		☐ Ovalized
		☐ Over/Under tolerance
		☐ Part Incorrect
		☐ Part Lost/Missing
		☐ Part Moved
		☐ Positioned Wrong
		☐ Power Loss/Surge
		☐ Pressure/Forced
		☐ Temperature/Cure
		☐ Weld
		☐ Wrong Stock Pulled
		☐ Other

Work Order ID 112762

Thursday, February 06, 2014 12:41:34 PM

112762

Page 2

Item ID: PB67-43001-225 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Bushing
 Start Date: 2/6/2014 Start Qty: 72.00 ***72*** Cust Item ID:
 Required Date: 2/20/2014 Req'd Qty: 72.00 ***72*** Customer:
 Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	Identify as per dwg & Stock Location: <i>Memo</i>	0.00							
130									
Packaging	Memo	0.00							
Packaging									
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.00							
Quality Control									

DAS
28
9-89

72x *14-2-12*

14-02-13

AA 14-02-12

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data ☐									
Equip/Tooling ☐									
Operator ☐									
Material ☐									
Setup ☐									
Other ☐									
Process ☐									
Supplier ☐									
Training ☐									
Unapproved ☐									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric to O/S ☐ Cracks ☐ Crushed/Crimped ☐ Cuffs ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Ripples in Bend ☐ Torque Waves in Extrusion ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damaged ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drill Holes ☐ Drawing ☐ Finish ☐ Folio	☐ Grain ☐ Hardware ☐ Inspection Incomplete ☐ Instructions Incomplete/Unclear ☐ Maintenance ☐ Mislabeled ☐ Misread ☐ Offset ☐ Out of Calibration ☐ Out of Sequence ☐ Outside Dimensions	☐ Ovalized ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge	☐ Pressure/Forced ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
---	---	---	--	---

Picklist Print

Thursday, February 06, 2014 1:06:26 PM

Page 1

Work Order ID: 112762

Parent Item: PB67-43001-225

Start Date: 2/6/2014

Required Date: 2/20/2014

Parent Item Name: Bushing

Start Qty: 72.00

Required Qty: 72.00

Comments: IPP Rev:A 08-06-26 new issue EC verified by:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

M6061T6R0.500

Purchased

No

f

1.0000

7.2

6061-T6 Round Bar .500"

• 563" C214/10211

Location

Loc Qty

Loc Code

MAT012

1

1

126852

x 7.2'

10025
14-02-12

6061T6R

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____



QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data ☐									
Equip/Tooling ☐									
Operator ☐									
Material ☐									
Setup ☐									
Other ☐									
Process ☐									
Supplier ☐									
Training ☐									
Unapproved ☐									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric to O/S ☐ Cracks ☐ Crushed/Crimped ☐ Cuffs ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Ripples in Bend ☐ Torque Waves in Extrusion ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damaged ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drill Holes ☐ Drawing ☐ Finish ☐ Folio	☐ Grain ☐ Hardware ☐ Inspection Incomplete ☐ Instructions Incomplete/Unclear ☐ Maintenance ☐ Mislabeled ☐ Misread ☐ Offset ☐ Out of Calibration ☐ Out of Sequence ☐ Outside Dimensions	☐ Ovalized ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
---	---	---	---




B67-43001-225 BUSHING

112762

mf

14-2-6



RELEASED
2009-09-24
MD

NOTES:

- 1) MATERIAL: 6061-T6 OR 6061-T62 TUBING
PER WW-T-700/6 OR AMS 4080 OR AMS 4082 OR
PER QQ-A-20/8 OR QQ-A-225/8
REF. DART SPEC. M6061T6T0.500W.125
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 0.01 lbs

C	REDRAWN PREMIER AVIATION DRAWING IAW DART QSI 018 AND QSI 043. FOR PREVIOUS REVISIONS, REFER TO PAGE 18 OF PREMIER AVIATION DRAWING No. B67-43001. REASON: SEE PAR#09-011.		MB	09.02.24
REV.	DESCRIPTION		BY	DATE
DESIGN	RW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
DRAWN				
CHECKED	AS	DRAWING NO.	REV. C	
MFG. APPR.		B67-43001-225	SHEET 1 OF 1	
APPROVED		TITLE	SCALE	
DE APPR.	N/A	BUSHING	NTS	
DATE	08.02.24			
COPYRIGHT © 1995 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.				

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Work Order Update ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">Skid-tube ☐</td> <td style="width: 25%;">Crosstube ☐</td> <td style="width: 25%;">Water Jet ☐</td> <td style="width: 25%;">Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data									
Equip/Tooling									
Operator									
Material									
Setup									
Other									
Process									
Supplier									
Training									
Unapproved									

FAULT CATEGORY

Landing Gear	General	Other	Other
☐ Bending	☐ Bend	☐ Grain	☐ Ovalized
☐ Centre Not Concentric to O/S	☐ BOM/Route	☐ Hardware	☐ Over/Under tolerance
☐ Cracks	☐ Broken/Damaged	☐ Inspection Incomplete	☐ Part Incorrect
☐ Crushed/Crimped.	☐ Burrs	☐ Instructions Incomplete/Unclear	☐ Part Lost/Missing
☐ Cuffs	☐ Contamination	☐ Maintenance	☐ Part Moved
☐ Heat Treat	☐ Countersink	☐ Mislabeled	☐ Positioned Wrong
☐ Inspection Strip in Tube	☐ Cut Too Short	☐ Misread	☐ Power Loss/Surge
☐ Ripples in Bend	☐ Drill Holes	☐ Offset	☐ Pressure/Forced
☐ Torque Waves in Extrusion	☐ Drawing	☐ Out of Calibration	☐ Temperature/Cure
☐ Turning Sequence	☐ Finish	☐ Out of Sequence	☐ Weld
☐ Wave/Twist in Tube	☐ Folio	☐ Outside Dimensions	☐ Wrong Stock Pulled
			☐ Other

